

[1]

PRODUCTION QUALITY ASSURANCE NOTIFICATION



[2]

Equipment or Protective System intended for use in Potentially Explosive Atmospheres Directive 94/9/EC

[3]

Notification Number:

11 ATEX Q134762 Rev. 0

[4]

Equipment or Protective System or Components as listed:

Signaling and Communication Devices
Intrinsic Safety “i”
Encapsulation “m”
Increased Safety “e”
Flameproof Enclosure “d”
Dust Protection by Enclosure “tD”
Equipment Dust Ignition Protection by Enclosure “tb”

[5]

Applicant:

Federal Signal Corporation
2645 Federal Signal Drive
University Park, IL 60484 USA

[6]

Manufacturer:

Same as Applicant

[7]

UL International Demko A/S notified body number 0539 for Annex IV in accordance with Article 9 of the Council Directive 94/9/EC of 23 March 1994, notifies to the applicant that the actual manufacturer has a production quality system which complies to Annex IV of the Directive.

[8]

This notification is based on audit report No.

11NK04163, Dated 2011-06-03

This notification can be withdrawn if the manufacturer no longer satisfies the requirements of Annex IV. The Manufacturer is obliged to inform UL International Demko A/S of any changes in their ISO 9001:2008 registration or other aspects upon which this notification has been given.

Results of periodic re-assessment of the quality system are a part of this notification.

[9]

This notification is valid until:

2014-03-31

and can be withdrawn if the manufacturer does not satisfy the production quality assurance re-assessment.

[10]

According to Article 10[1] of the Directive 94/9/EC the CE marking shall be followed by the identification number 0539 identifying the notified body involved in the production control stage.

Certification Manager

Jan-Erik Storgaard

This notification may only be reproduced in its entirety and without any change

Date of issue: 2011-06-07

Notified Body

UL International Demko A/S, Lyskaer 8, P.O. Box 514, DK-2730 Herlev, Denmark, Tel. +45 44 85 65 65, info.dk@dk.ul.com
www.ul-europe.com



the standard in safety

Underwriters
Laboratories